

CERTIFICATE OF COMPLIANCE

Certificate Number 2023-09-27-E490689
Report Reference E490689-D1000-1/A0/C0-UL
Date 2023-09-27

Issued to: Belden Hirschmann Industries (Suzhou) Ltd
Applicant Company: 333 YANHU RD HUAQIAO TOWN
KUNSHAN, JIANGSU, 215332 China

Listed Company: Same as Applicant

**This is to certify that
representative samples of**

Industrial Ethernet Lemur Rail Switch
LRS30-7TX/3SFP/1C, LRS40-7TX/3SFP/1C, LRS32-
7TX/3SFP/1C, LRS42-7TX/3SFP/1C, LRS32-7TX/3SFP/1C-HP,
LRS42-7TX/3SFP/1C-HP

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 61010-1, 3rd Edition, May 11, 2012, Revised July 19, 2019,
CAN/CSA-C22.2 No. 61010-1(2012-05), 3rd Edition, with
revisions through 2018-11


Additional Standards: UL 61010-2-201, 2nd Edition, Issue date 2018-05-14, Revision
date 2022-08-08.
CAN/CSA-C22.2 No. 61010-2-201:18, 2nd Edition, Issue date
2018-02

Additional Information: See the UL Online Certifications Directory at
www.ul.com/database for additional information.

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/about/locations/>

